# VENKAT SAI ENTERPRISES PRIVATE LIMITED

GSTIN : 36AAECV5358D1Z9 Website : https://www.venkatsaienterprises.com

(Authorised Dealer for JOHN DEERE INDIA PRIVATE LIMITED)

**Branch:** Kadem Road, Beside HP Petrol Pump, Vill: Ponkal, Jannaram, TS

Admin & Regd Off:8-6-300 Kothirampur Karimnagar Telangana 505001

## JOBCARD GST INVOICE

**C.Code :**
**C.Name :** DORISHETTI MAHESH
S/o or W/o : DORISHETTI SHEKHAR
H.NO:2-117/1.GANDHINAGAR.RAINDLAGUDA
JANNARAM
MANCHERIAL -504205
Telangana PH: 8688272764

**GSTIN :**

**Bill No. :** JNR-JI-27 1116
**Date :** 10-11-2026
**JC NO :** JNRWSJCB27 451
**JC Date :** 10-Nov-26 12:00:00 AM
**Chassis No :** 1VY5039DTNA012632
**Model No :** 5039 D
**Reg No :** AP39UB2354

| SNo | Item Code | HSN | Item Description | Qty | Wty | Foc | Unit Rate | Assesable Value | CGST | | SGST | | IGST | | Amount |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | Rs | % | Rs | % | Rs | % | |
| 1 | R141337 | 87089900 | SEAL | 2.00 | | | 396.00 | 671.19 | 60.41 | 9.0 | 60.41 | 9.0 | 0.00 | 0.0 | 792.00 |
| 2 | R140561 | 87089900 | WASHER | 2.00 | | | 14.00 | 23.73 | 2.14 | 9.0 | 2.14 | 9.0 | 0.00 | 0.0 | 28.00 |
| 3 | RE508953 | 84212300 | INSERT FILTER PRIMARY | 1.00 | | | 138.00 | 116.95 | 10.53 | 9.0 | 10.53 | 9.0 | 0.00 | 0.0 | 138.00 |
| 4 | RE508954 | 84212300 | FUEL FILTER | 1.00 | | | 137.00 | 116.10 | 10.45 | 9.0 | 10.45 | 9.0 | 0.00 | 0.0 | 137.00 |
| 5 | R178402 | 73182200 | WASHER, WASHER | 4.00 | | | 46.00 | 155.93 | 14.03 | 9.0 | 14.03 | 9.0 | 0.00 | 0.0 | 184.00 |
| 6 | R503808 | 87089900 | DRAIN PLUG, PLUG, DRAI | 1.00 | | | 72.00 | 61.02 | 5.49 | 9.0 | 5.49 | 9.0 | 0.00 | 0.0 | 72.00 |
| 7 | R120247 | 73182200 | RING | 1.00 | | | 32.00 | 27.12 | 2.44 | 9.0 | 2.44 | 9.0 | 0.00 | 0.0 | 32.00 |
| 8 | PY10853 | 27101990 | JD GREASE GARD PREMI | 0.10 | | | 2,832.00 | 240.00 | 21.60 | 9.0 | 21.60 | 9.0 | 0.00 | 0.0 | 283.20 |
| | | | **Spares Total** | **12** | | | | **1,412.02** | **127.09** | | **127.09** | | **0.00** | | **1,666.20** |
| | **Services** | | | | | | | | | | | | | | |
| 1 | Hydraulic Arm / Seals Replacement 1 side-5D<br>HSN Code :998719 | | | 1 | | | 500.00 | 423.73 | 38.14 | 9.0 | 38.14 | 9.0 | 0.00 | 0.0 | 500.00 |
| 2 | Steering Arm-5D<br>HSN Code :998719 | | | 1 | | | 200.00 | 169.49 | 15.25 | 9.0 | 15.25 | 9.0 | 0.00 | 0.0 | 200.00 |
| | | | **Service Total** | **2.00** | 0.00 | 0.00 | | **593.22** | **53.39** | | **53.39** | | **0.00** | | **700.00** |
| | | | **Grand Total :** | **14** | | | | **2,005.26** | **180.48** | | **180.48** | | **0.00** | | **2,366.00** |

GSTIN:36AAECV5358D1Z9
CIN-U34103TG2013PTC089369

**Rupees :** Two Thousand Three Hundred and Sixty Six Only

Note : Parts once sold will not be taken back or exchange.

Subject to KARIMNAGAR Jurisdiction

Bank Processing Charges :

**Spares.Total :** **1,666.20**
**Lab.Charges :** **700.00**
**Round Off :** **-0.20**
**Total :** **2,366.00**

This is Computer Generated Invoice Signature not Required