VENKAT SAI ENTERPRISES PRIVATE LIMITED

GSTIN : 36AAECV5358D1Z9

Website : https://www.venkatsaienterprises.com

(Authorised Dealer for JOHN DEERE INDIA PRIVATE LIMITED)

Branch: # 5-1/3 , Andhra Colony- Uthkur Main Road, LUXETTIPET, TS

Admin & Regd Off:8-6-300 Kothirampur Karimnagar Telangana 505001

JOBCARD GST INVOICE

C.Code :

C.Name : BODAKUNTI KOTANNA-39147/A
S/o or W/o : RAJLINGU
VENKATRAOPET
LUXETTIEPT
MANCHIRIAL -504215
Telangana PH: 9100816153

GSTIN :

Bill No. : LXT-JI-27 11
Date : 06-04-2026
JC NO : LXTWSJCB27 6
JC Date : 04-Apr-26 12:00:00 AM
Chassis No : 1PY5042DEMA029979
Model No : 5042 LPY
Reg No : TS19TA3335

SNo	Item Code	HSN	Item Description	Qty	Wty	Foc	Unit Rate	Assesable Value	CGST		SGST		IGST		Amount
									Rs	%	Rs	%	Rs	%	
1	SU69776	84831099	SHAFT, SHAFT-(R141313)	1.00			4,233.00	3,587.29	322.86	9.0	322.86	9.0	0.00	0.0	4,233.00
2	R140550	87089900	BUSHING DU 55/60X40	2.00			224.00	379.66	34.17	9.0	34.17	9.0	0.00	0.0	448.00
3	R141321	87089900	BUSHING	2.00			243.00	411.86	37.07	9.0	37.07	9.0	0.00	0.0	486.00
4	R140574	87089900	DOWEL PIN	1.00			27.00	22.88	2.06	9.0	2.06	9.0	0.00	0.0	27.00
5	R141335	73182200	WASHER	2.00			156.00	264.41	23.80	9.0	23.80	9.0	0.00	0.0	312.00
6	R141337	87089900	SEAL	2.00			388.00	657.63	59.19	9.0	59.19	9.0	0.00	0.0	776.00
7	R182404	87089900	SNAP RING	2.00			29.00	49.15	4.42	9.0	4.42	9.0	0.00	0.0	58.00
8	R141339	87089900	LOCK WASHER	1.00			182.00	154.24	13.88	9.0	13.88	9.0	0.00	0.0	182.00
9	R141340	87089900	O-RING	1.00			23.00	19.49	1.75	9.0	1.75	9.0	0.00	0.0	23.00
10	PYS10246	35061000	Liquid Gasket. LOCTITE 51	1.00			225.00	190.68	17.16	9.0	17.16	9.0	0.00	0.0	225.00
11	R140587	73182910	CIRCLIP RS D6	2.00			4.00	6.78	0.61	9.0	0.61	9.0	0.00	0.0	8.00
12	PYS10246	35061000	Liquid Gasket. LOCTITE 51	1.00			225.00	190.68	17.16	9.0	17.16	9.0	0.00	0.0	225.00
			Spares Total	**18**				**5,934.74**	**534.13**		**534.13**		**0.00**		**7,003.00**
			Services												
1	Hydraulic Arm / Seals Replacement 1 side-5D HSN Code :998719			1			500.00	423.73	38.14	9.0	38.14	9.0	0.00	0.0	500.00
2	Hydraulic Arm / Seals Replacement 1 side-5D HSN Code :998719			1			500.00	423.73	38.14	9.0	38.14	9.0	0.00	0.0	500.00
3	General Check up HSN Code :998719			1			300.00	254.24	22.88	9.0	22.88	9.0	0.00	0.0	300.00
4	Steering Arm-5D HSN Code :998719			1			200.00	169.49	15.25	9.0	15.25	9.0	0.00	0.0	200.00
			Service Total	**4.00**	0.00	0.00		**1271.19**	**114.41**		**114.41**		**0.00**		**1,500.00**
			Grand Total :	**22**				**7,205.94**	**648.54**		**648.54**		**0.00**		**8,503.00**

GSTIN:36AAECV5358D1Z9
CIN-U34103TG2013PTC089369

Rupees : Eight Thousand Five Hundred and Three Only

Note : Parts once sold will not be taken back or exchange.

Subject to KARIMNAGAR Jurisdiction

Bank Processing Charges :

Spares.Total : 7,003.00
Lab.Charges : 1,500.00
Round Off : 0.00
Total : 8,503.00

This is Computer Generated Invoice Signature not Required