

# VENKAT SAI ENTERPRISES PRIVATE LIMITED

GSTIN : 36AAECV5358D1Z9

Website : <https://www.venkatsaienterprises.com>

(Authorised Dealer for JOHN DEERE INDIA PRIVATE LIMITED)

**Branch:** Sy.no: 642/2/A/2/1, Siddipet Road, HUSNABAD, SIDDIPET, TS-50546

Admin & Regd Off:8-6-300 Kothirampur Karimnagar Telangana 505001

## JOB CARD GST INVOICE

<b>C.Code :</b> <b>C.Name :</b> KUNDELLA SURESH S/o or W/o : YADAGIRI H NO 3-34/1, AKKANNAPETA AKKANNAPET SIDDIPET Telangana	<b>Bill No. :</b> HSB-JI-27 10 <b>Date :</b> 03-04-2026 <b>JC NO :</b> HSBWSJCB27 8 <b>JC Date :</b> 03-Apr-26 12:00:00 AM <b>Chassis No :</b> 1XPRB03BLRR000333 <b>Model No :</b> 1.1M Round Baler RB0311 Auto Twine <b>Reg No :</b>
--	---

**GSTIN :**

SNo	Item Code	HSN	Item Description	Qty	Wty	Foc	Unit Rate	Assesable Value	CGST		SGST		IGST		Amount
									Rs	%	Rs	%	Rs	%	
1	5GE101FPS	84339000	FLANGE-PUMP SIDE	1.00			313.00	298.10	7.45	2.5	7.45	2.5	0.00	0.0	313.00
2	5GE104SRO	73182910	SNAP RING (OCP #25)	1.00			4.00	3.39	0.31	9.0	0.31	9.0	0.00	0.0	4.00
3	5GE104BE5	84821011	BEARING-6205 2RS1	1.00			612.00	518.64	46.68	9.0	46.68	9.0	0.00	0.0	612.00
<b>Spares Total</b>				<b>3</b>				<b>820.12</b>	<b>54.44</b>			<b>54.44</b>	<b>0.00</b>		<b>929.00</b>
<b>Services</b>															
1	D- Plate Repair & Replacement HSN Code :998719			1			2,000.00	1,694.92	152.54	9.0	152.54	9.0	0.00	0.0	2,000.00
<b>Service Total</b>				<b>1.00</b>	0.00	0.00		<b>1694.92</b>	<b>152.54</b>			<b>152.54</b>	<b>0.00</b>		<b>2,000.00</b>
<b>Grand Total :</b>				<b>4</b>				<b>2,515.05</b>	<b>206.98</b>			<b>206.98</b>	<b>0.00</b>		<b>2,929.00</b>

GSTIN36AAECV5358D1Z9  
CIN-U34103TG2013PTC089369

**Rupees :** Two Thousand Nine Hundred and Twenty Nine Only  
Note : Parts once sold will not be taken back or exchange.

Subject to KARIMNAGAR Jurisdiction

Bank Processing Charges :

<b>Spares.Total :</b>	<b>929.00</b>
<b>Lab.Charges :</b>	<b>2,000.00</b>
<b>Round Off :</b>	<b>0.00</b>
<b>Total :</b>	<b>2,929.00</b>

This is Computer Generated Invoice Signature not Required