

VENKAT SAI ENTERPRISES PRIVATE LIMITED

GSTIN : 36AAECV5358D1Z9

Website : <https://www.venkatsaienterprises.com>

(Authorised Dealer for JOHN DEERE INDIA PRIVATE LIMITED)

Branch: 1-1/2E- Beside Mount Carmel School, Vill: Dharur, JAGTIAL, TS

Admin & Regd Off:8-6-300 Kothirampur Karimnagar Telangana 505001

JOB CARD GST INVOICE

C.Code :

C.Name : DAWA THIRUPATHI-(OC)

S/o or W/o : GANGAJALA

GOPALRAOPET

JAGTIAL

JAGTIAL

Telangana

-505327

PH: 9849194237

Bill No. : JGL-JI-27 13

Date : 03-04-2026

JC NO : JGLFSJCB27 4

JC Date : 03-Apr-26 12:00:00 AM

Chassis No : PY5310S025124

Model No : 5310

Reg No : AP25Q3019-KTP

GSTIN :

| SNo | Item Code | HSN | Item Description | Qty | Wty | Foc | Unit Rate | Assesable Value | CGST | | SGST | | IGST | | Amount |
|----------------------|---|----------|---------------------------|-------------|------|------|-----------|-----------------|---------------|-----|--------|---------------|------|-------------|-----------------|
| | | | | | | | | | Rs | % | Rs | % | Rs | % | |
| 1 | L35542 | 87089900 | GUIDE | 1.00 | | | 134.00 | 113.56 | 10.22 | 9.0 | 10.22 | 9.0 | 0.00 | 0.0 | 134.00 |
| 2 | SJ15582 | 40169330 | SEAL. REAR AXLE SEAL | 1.00 | | | 422.00 | 357.63 | 32.19 | 9.0 | 32.19 | 9.0 | 0.00 | 0.0 | 422.00 |
| 3 | L77363 | 73181500 | SCREW.SPECIAL W/FLAN | 1.00 | | | 97.00 | 82.20 | 7.40 | 9.0 | 7.40 | 9.0 | 0.00 | 0.0 | 97.00 |
| 4 | AL39391 | 40169320 | SEAL | 1.00 | | | 334.00 | 283.05 | 25.47 | 9.0 | 25.47 | 9.0 | 0.00 | 0.0 | 334.00 |
| 5 | L156476 | 87085000 | PLATE. LOCK | 1.00 | | | 74.00 | 70.48 | 1.76 | 2.5 | 1.76 | 2.5 | 0.00 | 0.0 | 74.00 |
| 6 | R212825 | 73182200 | THRUST WASHER. PH-BZ | 1.00 | | | 48.00 | 40.68 | 3.66 | 9.0 | 3.66 | 9.0 | 0.00 | 0.0 | 48.00 |
| 7 | PY10854 | 27101990 | JD GREASE GARD PREMI | 1.00 | | | 290.00 | 245.76 | 22.12 | 9.0 | 22.12 | 9.0 | 0.00 | 0.0 | 290.00 |
| 8 | PYS10246 | 35061000 | Liquid Gasket. LOCTITE 51 | 1.00 | | | 225.00 | 190.68 | 17.16 | 9.0 | 17.16 | 9.0 | 0.00 | 0.0 | 225.00 |
| 9 | RE73206 | 84821090 | BALL BEARING. BALL BEA | 1.00 | | | 788.00 | 667.80 | 60.10 | 9.0 | 60.10 | 9.0 | 0.00 | 0.0 | 788.00 |
| 10 | RE73204 | 84821090 | BEARING. BEARING. TAP | 1.00 | | | 774.00 | 655.93 | 59.03 | 9.0 | 59.03 | 9.0 | 0.00 | 0.0 | 774.00 |
| 11 | RE73205 | 40169320 | SEAL. HUB | 1.00 | | | 573.00 | 485.59 | 43.70 | 9.0 | 43.70 | 9.0 | 0.00 | 0.0 | 573.00 |
| 12 | R114016 | 73181600 | NUT. CASTLE | 1.00 | | | 194.00 | 164.41 | 14.80 | 9.0 | 14.80 | 9.0 | 0.00 | 0.0 | 194.00 |
| 13 | R197038 | 73182400 | COTTER PIN | 1.00 | | | 11.00 | 9.32 | 0.84 | 9.0 | 0.84 | 9.0 | 0.00 | 0.0 | 11.00 |
| 14 | PY7053 | 84821090 | BEARING | 1.00 | | | 1,342.00 | 1,137.29 | 102.36 | 9.0 | 102.36 | 9.0 | 0.00 | 0.0 | 1,342.00 |
| Spares Total | | | | 14 | | | | 4,504.38 | 400.81 | | | 400.81 | | 0.00 | 5,306.00 |
| Services | | | | | | | | | | | | | | | |
| 1 | Rear Axle per side-5E HSN Code :998719 | | | 1 | | | 2,300.00 | 1,949.15 | 175.42 | 9.0 | 175.42 | 9.0 | 0.00 | 0.0 | 2,300.00 |
| 2 | Light Switch/Horn /Switches / Sensors each-5E HSN Code :998719 | | | 1 | | | 200.00 | 169.49 | 15.25 | 9.0 | 15.25 | 9.0 | 0.00 | 0.0 | 200.00 |
| Service Total | | | | 2.00 | 0.00 | 0.00 | | 2118.64 | 190.67 | | | 190.67 | | 0.00 | 2,500.00 |
| Grand Total : | | | | 16 | | | | 6,623.02 | 591.48 | | | 591.48 | | 0.00 | 7,806.00 |

GSTIN:36AAECV5358D1Z9
CIN-U34103TG2013PTC089369

Rupees : Seven Thousand Eight Hundred and Six Only
Note : Parts once sold will not be taken back or exchange.

Subject to KARIMNAGAR Jurisdiction

Bank Processing Charges :

Spares.Total : 5,306.00
Lab.Charges : 2,500.00
Round Off : 0.00
Total : 7,806.00

This is Computer Generated Invoice Signature not Required