

VENKAT SAI ENTERPRISES PRIVATE LIMITED

GSTIN : 36AAECV5358D1Z9

Website : <https://www.venkatsaienterprises.com>

(Authorised Dealers for JOHN DEERE INDIA PRIVATE LIMITED)

Branch: H.No: 6-58 , Mangapeta Road, MULUGU, Dist: JS Bhupalpally, TS

AdminOff: #8-6-300, Kothirampur, Karimnagar, Telangana, 505001

RegdOff: Sy.No.141/B, Kandlakoya, Medchal, Malkajgiri, TS-501401

JOB CARD GST INVOICE

C.Code : 56817
C.Name : THATI SHAILAJA
 S/o or W/o : HANMANTHARAO
 H.NO. 10-295, CHALVAI
 GOVINDARAOPETA
 MULUGU -506344
 Telangana PH: 7095757462

Bill No. : MLG-JI-26 3786
Date : 18-02-2026
JC NO : MLGFSJCB26 2527
JC Date : 18-Feb-26 12:00:00 AM
Chassis No : 1PY5210EASL029465
Model No : 5210 4WD GEAR PRO
Reg No :

GSTIN :

| SNo | Item Code | HSN | Item Description | Qty | Wty | Foc | Unit Rate | Assesable Value | CGST | | SGST | | IGST | | Amount |
|----------------------|---|----------|---------------------------|-------------|------|------|-----------|-----------------|---------------|-----|---------------|-----|-------------|-----|-----------------|
| | | | | | | | | | Rs | % | Rs | % | Rs | % | |
| 1 | R34404 | 40169320 | PACKING. O-RING | 1.00 | | | 7.00 | 5.93 | 0.53 | 9.0 | 0.53 | 9.0 | 0.00 | 0.0 | 7.00 |
| 2 | P51212 | 40169320 | O-RING | 2.00 | | | 9.00 | 15.25 | 1.37 | 9.0 | 1.37 | 9.0 | 0.00 | 0.0 | 18.00 |
| 3 | R32507 | 73182990 | RING.RETAINING | 1.00 | | | 6.00 | 5.08 | 0.46 | 9.0 | 0.46 | 9.0 | 0.00 | 0.0 | 6.00 |
| 4 | H21957 | 40169330 | RING-O | 1.00 | | | 21.00 | 17.80 | 1.60 | 9.0 | 1.60 | 9.0 | 0.00 | 0.0 | 21.00 |
| 5 | R105216 | 73182200 | WASHER | 1.00 | | | 7.00 | 5.93 | 0.53 | 9.0 | 0.53 | 9.0 | 0.00 | 0.0 | 7.00 |
| 6 | PYS10246 | 35061000 | Liquid Gasket. LOCTITE 51 | 2.00 | | | 225.00 | 381.36 | 34.32 | 9.0 | 34.32 | 9.0 | 0.00 | 0.0 | 450.00 |
| 7 | 19M7866 | 73181500 | SCREW. FLANGED. METR | 6.00 | | | 7.00 | 35.59 | 3.20 | 9.0 | 3.20 | 9.0 | 0.00 | 0.0 | 42.00 |
| 8 | RE45607 | 87089900 | TUBE. FRONT. ASSEMBLY | 1.00 | | | 355.00 | 300.85 | 27.08 | 9.0 | 27.08 | 9.0 | 0.00 | 0.0 | 355.00 |
| 9 | RE45609 | 87089900 | TUBE. REAR. ASSEMBLY | 1.00 | | | 451.00 | 382.20 | 34.40 | 9.0 | 34.40 | 9.0 | 0.00 | 0.0 | 451.00 |
| Spares Total | | | | 16 | | | | 1,150.02 | 103.49 | | 103.49 | | 0.00 | | 1,357.00 |
| Services | | | | | | | | | | | | | | | |
| 1 | Wty- Power Steering Cylinder Seal kit HSN Code :998719 | | | | 1 | | 280.00 | 0.00 | 0.00 | 9.0 | 0.00 | 9.0 | 0.00 | 0.0 | 0.00 |
| Service Total | | | | 0.00 | 1.00 | 0.00 | | .00 | 0.00 | | 0.00 | | 0.00 | | 0.00 |
| Grand Total : | | | | 17 | | | | 1,149.99 | 103.49 | | 103.49 | | 0.00 | | 1,357.00 |

GSTIN:36AAECV5358D1Z9
 CIN-U34103TG2013PTC089369

Rupees : One Thousand Three Hundred and Fifty Seven Only
 Note : Parts once sold will not be taken back or exchange.

All Subject to HYDERABAD Jurisdiction only.

Bank Processing Charges :

Spares.Total : 1,357.00
Lab.Charges : 0.00
Round Off : 0.00
Total : 1,357.00

This is Computer Generated Invoice Signature not Required