

VENKAT SAI ENTERPRISES PRIVATE LIMITED

GSTIN : 36AAECV5358D1Z9

Website : <https://www.venkatsaienterprises.com>

(Authorised Dealers for JOHN DEERE INDIA PRIVATE LIMITED)

Branch: HNo: 4-347/3, Madhuranagar, Gangadhara 'X' Road, Karimnagar, TS-

AdminOff: #8-6-300, Kothirampur, Karimnagar, Telangana, 505001

RegdOff: Sy.No.141/B, Kandlakoya, Medchal, Malkajgiri, TS-501401

JOB CARD GST INVOICE

C.Code :
C.Name : BODDU SHEKAR(29730/A)
 S/o or W/o : DAYANDAM
 KONDAPOOR
 KODIMYAL
 JAGITYAL -505501
 Telangana PH: 8790291204

Bill No. : GDR-JI-26 2745
Date : 23-02-2026
JC NO : GDRFSJCB26 1417
JC Date : 23-02-2026 00:00:00
Chassis No : 1PY5310EVKA043308
Model No : 5310 4WD
Reg No :

GSTIN :

| SNo | Item Code | HSN | Item Description | Qty | Wty | Foc | Unit Rate | Assesable Value | CGST | | SGST | | IGST | | Amount | |
|----------------------|---|----------|---------------------------|-------------|-------------|-------------|-----------|-----------------|---------------|-----|--------|---------------|------|-------------|----------|-----------------|
| | | | | | | | | | Rs | % | Rs | % | Rs | % | | |
| 1 | SJ12595 | 40169320 | SEAL. SEAL. 22X32X7 | 1.00 | | | 35.00 | 29.66 | 2.67 | 9.0 | 2.67 | 9.0 | 0.00 | 0.0 | 35.00 | |
| 2 | PY10850 | 27101990 | ENGINE OIL (8.5L CAN) | 1.00 | | | 3,430.00 | 2,906.78 | 261.61 | 9.0 | 261.61 | 9.0 | 0.00 | 0.0 | 3,430.00 | |
| 3 | RE507204 | 84212300 | OIL FILTER | 1.00 | | | 390.00 | 330.51 | 29.75 | 9.0 | 29.75 | 9.0 | 0.00 | 0.0 | 390.00 | |
| 4 | RE508953 | 84212300 | INSERT FILTER PRIMARY | 1.00 | | | 125.00 | 105.93 | 9.53 | 9.0 | 9.53 | 9.0 | 0.00 | 0.0 | 125.00 | |
| 5 | RE508954 | 84212300 | INSERT FILTER SECONDA | 1.00 | | | 132.00 | 111.86 | 10.07 | 9.0 | 10.07 | 9.0 | 0.00 | 0.0 | 132.00 | |
| 6 | R120247 | 73182200 | RING. WASHER | 1.00 | | | 30.00 | 25.42 | 2.29 | 9.0 | 2.29 | 9.0 | 0.00 | 0.0 | 30.00 | |
| 7 | R140561 | 87089900 | WASHER | 2.00 | | | 12.00 | 20.34 | 1.83 | 9.0 | 1.83 | 9.0 | 0.00 | 0.0 | 24.00 | |
| 8 | SJ16221 | 84213920 | Air Cleaner. ASSEMBLY 7 I | 1.00 | | | 3,116.00 | 2,640.68 | 237.66 | 9.0 | 237.66 | 9.0 | 0.00 | 0.0 | 3,116.00 | |
| 9 | SU22079 | 87089900 | HEAT SHIELD. RH | 1.00 | | | 542.00 | 459.32 | 41.34 | 9.0 | 41.34 | 9.0 | 0.00 | 0.0 | 542.00 | |
| 10 | SU32121 | 40169100 | BOOT. GEARSHIFT AND R | 2.00 | | | 96.00 | 162.71 | 14.64 | 9.0 | 14.64 | 9.0 | 0.00 | 0.0 | 192.00 | |
| 11 | R139947 | 87089900 | TIE BAND | 2.00 | | | 10.00 | 16.95 | 1.53 | 9.0 | 1.53 | 9.0 | 0.00 | 0.0 | 20.00 | |
| 12 | 21M7292 | 73181500 | SCREW. CR PAN HEAD. M | 2.00 | | | 7.00 | 11.86 | 1.07 | 9.0 | 1.07 | 9.0 | 0.00 | 0.0 | 14.00 | |
| Spares Total | | | | 16 | | | | 6,822.02 | 613.99 | | | 613.99 | | 0.00 | | 8,050.00 |
| Services | | | | | | | | | | | | | | | | |
| 1 | General Service - Engine Oil, Engine Oil Filter & Fuel Filter Change-5D | | | 1 | | | 350.00 | 296.61 | 26.69 | 9.0 | 26.69 | 9.0 | 0.00 | 0.0 | 350.00 | |
| 2 | Engine Push Rod-5D HSN Code :998719 | | | 1 | | | 600.00 | 508.47 | 45.76 | 9.0 | 45.76 | 9.0 | 0.00 | 0.0 | 600.00 | |
| 3 | MFWD Pinion Shaft Seal Replacement-5E HSN Code :998719 | | | 1 | | | 300.00 | 254.24 | 22.88 | 9.0 | 22.88 | 9.0 | 0.00 | 0.0 | 300.00 | |
| Service Total | | | | 3.00 | 0.00 | 0.00 | | 1059.32 | 95.33 | | | 95.33 | | 0.00 | | 1,250.00 |
| Grand Total : | | | | 19 | | | | 7,881.34 | 709.32 | | | 709.32 | | 0.00 | | 9,300.00 |

GSTIN:36AAECV5358D1Z9
 CIN-U34103TG2013PTC089369

Rupees : Nine Thousand and Three Hundred Only
 Note : Parts once sold will not be taken back or exchange.

All Subject to HYDERABAD Jurisdiction only.

Bank Processing Charges :

Spares.Total : 8,050.00
Lab.Charges : 1,250.00
Round Off : 0.00
Total : 9,300.00

This is Computer Generated Invoice Signature not Required