

VENKAT SAI ENTERPRISES PRIVATE LIMITED

GSTIN : 36AAECV5358D1Z9

Website : <https://www.venkatsaienterprises.com>

(Authorised Dealer for JOHN DEERE INDIA PRIVATE LIMITED)

Branch: 8-82/7/18/A/5/1, Bypass Road, KARIMNAGAR,TS- 505001,
Admin & Regd Off:8-6-300 Kothirampur Karimnagar Telangana 505001

JOB CARD GST INVOICE

C.Code :
C.Name : KUNCHAM NARSIMHULU(31143/A)
S/o or W/o : GURUVIAH
SUBHASHNAGAR
KARIMNAGAR
KARIMNAGAR5
Telangana

-505001
PH: 9912376803

Bill No. : KRM-JI-27 83
Date : 11-04-2026
JC NO : KRMWSJCB27 36
JC Date : 10-Apr-26 12:00:00 AM
Chassis No : 1VY5105DTKA012790
Model No : 5105 D.
Reg No : TS19T9922

GSTIN :

| SNo | Item Code | HSN | Item Description | Qty | Wty | Foc | Unit Rate | Assesable Value | CGST | | SGST | | IGST | | Amount |
|----------------------|--|----------|--------------------------|-------------|------|------|-----------|-----------------|---------------|-----|--------|---------------|------|-------------|-----------------|
| | | | | | | | | | Rs | % | Rs | % | Rs | % | |
| 1 | PY10852 | 27101990 | ENGINE OIL (6.5L CAN) | 1.00 | | | 2,631.00 | 2,229.66 | 200.67 | 9.0 | 200.67 | 9.0 | 0.00 | 0.0 | 2,631.00 |
| 2 | RE507204 | 84212300 | OIL FILTER | 1.00 | | | 390.00 | 330.51 | 29.75 | 9.0 | 29.75 | 9.0 | 0.00 | 0.0 | 390.00 |
| 3 | RE508953 | 84212300 | INSERT FILTER PRIMARY | 1.00 | | | 125.00 | 105.93 | 9.53 | 9.0 | 9.53 | 9.0 | 0.00 | 0.0 | 125.00 |
| 4 | RE508954 | 84212300 | INSERT FILTER SECONDA | 1.00 | | | 132.00 | 111.86 | 10.07 | 9.0 | 10.07 | 9.0 | 0.00 | 0.0 | 132.00 |
| 5 | R140561 | 87089900 | WASHER | 2.00 | | | 12.00 | 20.34 | 1.83 | 9.0 | 1.83 | 9.0 | 0.00 | 0.0 | 24.00 |
| 6 | R120247 | 73182200 | RING. WASHER | 1.00 | | | 30.00 | 25.42 | 2.29 | 9.0 | 2.29 | 9.0 | 0.00 | 0.0 | 30.00 |
| 7 | RE182070 | 87089900 | PISTON | 1.00 | | | 1,329.00 | 1,126.27 | 101.36 | 9.0 | 101.36 | 9.0 | 0.00 | 0.0 | 1,329.00 |
| 8 | RE247599 | 87089900 | SEAL KIT. SEAL KIT. CYLI | 1.00 | | | 1,300.00 | 1,101.69 | 99.15 | 9.0 | 99.15 | 9.0 | 0.00 | 0.0 | 1,300.00 |
| 9 | SU32121 | 40169100 | BOOT. GEARSHIFT AND R | 2.00 | | | 96.00 | 162.71 | 14.64 | 9.0 | 14.64 | 9.0 | 0.00 | 0.0 | 192.00 |
| 10 | R139947 | 87089900 | TIE BAND | 2.00 | | | 10.00 | 16.95 | 1.53 | 9.0 | 1.53 | 9.0 | 0.00 | 0.0 | 20.00 |
| 11 | R140450 | 73182910 | SNAP RING | 1.00 | | | 349.00 | 295.76 | 26.62 | 9.0 | 26.62 | 9.0 | 0.00 | 0.0 | 349.00 |
| 12 | R177337 | 85361020 | 30 AMP FUSE | 3.00 | | | 14.00 | 35.59 | 3.20 | 9.0 | 3.20 | 9.0 | 0.00 | 0.0 | 42.00 |
| 13 | RE274951 | 39269099 | SWITCH. SWITCH. HORN | 1.00 | | | 81.00 | 68.64 | 6.18 | 9.0 | 6.18 | 9.0 | 0.00 | 0.0 | 81.00 |
| 14 | R178402 | 73182200 | WASHER | 2.00 | | | 43.00 | 72.88 | 6.56 | 9.0 | 6.56 | 9.0 | 0.00 | 0.0 | 86.00 |
| 15 | RE274942 | 85365020 | SWITCH. LIGHT SWITCH | 1.00 | | | 357.00 | 302.54 | 27.23 | 9.0 | 27.23 | 9.0 | 0.00 | 0.0 | 357.00 |
| Spares Total | | | | 21 | | | | 6,006.78 | 540.61 | | | 540.61 | | 0.00 | 7,088.00 |
| Services | | | | | | | | | | | | | | | |
| 1 | General Service - Engine Oil, Engine Oil Filter Fuel Filter Change-5D | | | 1 | | | 350.00 | 296.61 | 26.69 | 9.0 | 26.69 | 9.0 | 0.00 | 0.0 | 350.00 |
| 2 | Power Steering Cylinder Seal kit-5D HSN Code :998719 | | | 1 | | | 550.00 | 466.10 | 41.95 | 9.0 | 41.95 | 9.0 | 0.00 | 0.0 | 550.00 |
| Service Total | | | | 2.00 | 0.00 | 0.00 | | 762.71 | 68.64 | | | 68.64 | | 0.00 | 900.00 |
| Grand Total : | | | | 23 | | | | 6,769.46 | 609.25 | | | 609.25 | | 0.00 | 7,988.00 |

GSTIN:36AAECV5358D1Z9
CIN-U34103TG2013PTC089369

Rupees : Seven Thousand Nine Hundred and Eighty Eight Only
Note : Parts once sold will not be taken back or exchange.

Subject to KARIMNAGAR Jurisdiction

Bank Processing Charges :

Spares.Total : 7,088.00
Lab.Charges : 900.00
Round Off : 0.00
Total : 7,988.00

This is Computer Generated Invoice Signature not Required