

VENKAT SAI ENTERPRISES PRIVATE LIMITED

GSTIN : 36AAECV5358D1Z9

Website : <https://www.venkatsaienterprises.com>

(Authorised Dealers for JOHN DEERE INDIA PRIVATE LIMITED)

Branch: #13-108/2, Manthani Rd,Garepally,Kataram, Dist:JS Bhupalpally,TS

AdminOff: #8-6-300, Kothirampur, Karimnagar, Telangana, 505001

RegdOff: Sy.No.141/B, Kandlakoya, Medchal, Malkajgiri, TS-501401

JOB CARD GST INVOICE

C.Code : 47123
C.Name : LAMBU JEEVAN REDDY
 S/o or W/o : SANJEEV REDDY
 #2-120/a,BHUDEDAPALLY,(REGULAGUDEM)
 KATARAM
 JAYASHANKAR,505503
 Telangana
 PH: 9573270108

Bill No. : KTM-JI-26 1783
Date : 27-02-2026
JC NO : KTMFSJCB26 884
JC Date : 24-02-2026 00:00:00
Chassis No : 1VY5050DVNA057957
Model No : 5050D 4WD
Reg No :

GSTIN :

SNo	Item Code	HSN	Item Description	Qty	Wty	Foc	Unit Rate	Assesable Value	CGST		SGST		IGST		Amount
									Rs	%	Rs	%	Rs	%	
1	MPPY10098	87089900	PRODUCT IMPROVEMEN	0.00	1		450.00	0.00	0.00	9.0	0.00	9.0	0.00	0.0	0.00
2	PYS10347	38140010	PRECLEANER, ITW M CLE	0.00			385.00	0.00	0.00	9.0	0.00	9.0	0.00	0.0	0.00
3	PYS10345	35061000	ADHESIVE, PLEXUS MA 8	0.00			2,124.00	0.00	0.00	9.0	0.00	9.0	0.00	0.0	0.00
4	PYS10348	35061000	SEALANT, LOCTITE 577 -5	0.00			1,420.00	0.00	0.00	9.0	0.00	9.0	0.00	0.0	0.00
Spares Total				1	1			0.00	0.00		0.00		0.00		0.00
Services															
1	Wty-PIP 22VY086_VY_5D and 5E ULSD Fuel Tank Crack Repair		Wty-PIP 22VY086_VY_5D and 5E ULSD Fuel Tank Crack Repair Issue-Mandatory Safety		1		270.00	0.00	0.00	9.0	0.00	9.0	0.00	0.0	0.00
Service Total				0.00	1.00	0.00		.00	0.00		0.00		0.00		0.00
Grand Total :				1				0.00	0.00		0.00		0.00		0.00

GSTIN36AAECV5358D1Z9
 CIN-U34103TG2013PTC089369

Rupees : Zero Only

Note : Parts once sold will not be taken back or exchange.

All Subject to HYDERABAD Jurisdiction only.

Bank Processing Charges :

Spares.Total : 0.00
Lab.Charges : 0.00
Round Off : 0.00
Total : 0.00

This is Computer Generated Invoice Signature not Required