

VENKAT SAI ENTERPRISES PRIVATE LIMITED

GSTIN : 36AAECV5358D1Z9

Website : <https://www.venkatsaienterprises.com>

(Authorised Dealers for JOHN DEERE INDIA PRIVATE LIMITED)

Branch: #5-1-13/3, Near Indian oil Surya bunk, Maripeda, Mahabubabad, TS, 5

AdminOff: #8-6-300, Kothirampur, Karimnagar, Telangana, 505001

RegdOff: Sy.No.141/B, Kandlakoya, Medchal, Malkajgiri, TS-501401

JOB CARD GST INVOICE

C.Code : 17316
C.Name : MUDU SEETHA
 S/o or W/o : MUDU BALAJI
 YELLAMPETA(MANCHYATHANDA)
 MARIPEDA
 WARANGAL -.....
 Telangana PH: 9550890060

Bill No. : MRP-JI-26 942
Date : 19-02-2026
JC NO : MRPWSJCB26 333
JC Date : 17-02-2026 00:00:00
Chassis No : 1PY5042DLGA013928
Model No : 5042 LPY
Reg No :

GSTIN :

SNo	Item Code	HSN	Item Description	Qty	Wty	Foc	Unit Rate	Assesable Value	CGST		SGST		IGST		Amount	
									Rs	%	Rs	%	Rs	%		
1	SU69776	84831099	SHAFT, SHAFT-(R141313)	1.00			4,233.00	3,587.29	322.86	9.0	322.86	9.0	0.00	0.0	4,233.00	
2	R140550	87089900	BUSHING DU 55/60X40	2.00			224.00	379.66	34.17	9.0	34.17	9.0	0.00	0.0	448.00	
3	R141321	87089900	BUSHING	2.00			243.00	411.86	37.07	9.0	37.07	9.0	0.00	0.0	486.00	
4	R141309	87089900	ARM	2.00			2,836.00	4,806.78	432.61	9.0	432.61	9.0	0.00	0.0	5,672.00	
5	R141335	73182200	WASHER	2.00			156.00	264.41	23.80	9.0	23.80	9.0	0.00	0.0	312.00	
6	R141337	87089900	SEAL	2.00			388.00	657.63	59.19	9.0	59.19	9.0	0.00	0.0	776.00	
7	APIR140960	73194090	PIN, PIN, HEADED	1.00			38.00	32.20	2.90	9.0	2.90	9.0	0.00	0.0	38.00	
8	R109171	87081010	CLEVIS	1.00			272.00	259.05	6.48	2.5	6.48	2.5	0.00	0.0	272.00	
9	11M7023	73182400	PIN. COTTER	1.00			3.00	2.54	0.23	9.0	0.23	9.0	0.00	0.0	3.00	
10	SU41869	40169330	SEAL. HUB SEAL	1.00			395.00	334.75	30.13	9.0	30.13	9.0	0.00	0.0	395.00	
11	R182773	73209090	EXTENSION SPRING	1.00			39.00	33.05	2.97	9.0	2.97	9.0	0.00	0.0	39.00	
Spares Total				16				10,769.18	952.41			952.41		0.00		12,674.00
Services																
1	Hydraulic Arm / Seals Replacement 1 side-5D HSN Code :998719			1			500.00	423.73	38.14	9.0	38.14	9.0	0.00	0.0	500.00	
2	Hydraulic Arm / Seals Replacement 1 side-5D HSN Code :998719			1			500.00	423.73	38.14	9.0	38.14	9.0	0.00	0.0	500.00	
Service Total				2.00	0.00	0.00		847.46	76.28			76.28		0.00		1,000.00
Grand Total :				18				11,616.68	1,028.69			1,028.69		0.00		13,674.00

GSTIN:36AAECV5358D1Z9
 CIN-U34103TG2013PTC089369

Rupees : Thirteen Thousand Six Hundred and Seventy Four Only
 Note : Parts once sold will not be taken back or exchange.

All Subject to HYDERABAD Jurisdiction only.

Bank Processing Charges :

Spares.Total : 12,674.00
Lab.Charges : 1,000.00
Round Off : 0.00
Total : 13,674.00

This is Computer Generated Invoice Signature not Required