

# VENKAT SAI ENTERPRISES PRIVATE LIMITED

GSTIN : 36AAECV5358D1Z9

Website : <https://www.venkatsaienterprises.com>

(Authorised Dealers for JOHN DEERE INDIA PRIVATE LIMITED)

**Branch:** HNo:2-76/1&2, Karimnagar Rd- Rangampally, PEDDAPALLY, TS

**AdminOff:** #8-6-300, Kothirampur, Karimnagar, Telangana, 505001

**RegdOff:** Sy.No.141/B, Kandlakoya, Medchal, Malkajgiri, TS-501401

## JOB CARD GST INVOICE

**C.Code :**  
**C.Name :** EBC BRICKS COMPANY  
 S/o or W/o : SY NO 308 309 310,  
 KATNEPALLI,  
 SULTANABAD,  
 Peddapalli, -505525  
 Telangana PH: 09949044665

**Bill No. :** PDL-JI-26 4896  
**Date :** 05-03-2026  
**JC NO :** PDLFSJCB26 2544  
**JC Date :** 28-Feb-26 12:00:00 AM  
**Chassis No :** PY5310S029896  
**Model No :** 5310 SCV  
**Reg No :**

**GSTIN :** 36AAEPE9088Q1ZX

SNo	Item Code	HSN	Item Description	Qty	Wty	Foc	Unit Rate	Assesable Value	CGST		SGST		IGST		Amount
									Rs	%	Rs	%	Rs	%	
1	RE73204	84821090	BEARING. BEARING. TAP	2.00			774.00	1,311.86	118.07	9.0	118.07	9.0	0.00	0.0	1,548.00
2	RE73205	40169320	SEAL. HUB	2.00			573.00	971.19	87.41	9.0	87.41	9.0	0.00	0.0	1,146.00
3	RE73206	84821090	BALL BEARING. BALL BEA	2.00			788.00	1,335.59	120.20	9.0	120.20	9.0	0.00	0.0	1,576.00
4	R114016	73181600	NUT. CASTLE	2.00			194.00	328.81	29.59	9.0	29.59	9.0	0.00	0.0	388.00
5	R197038	73182400	COTTER PIN	1.00			11.00	9.32	0.84	9.0	0.84	9.0	0.00	0.0	11.00
6	R140438	87089900	BEARING CAP. HUB	1.00			84.00	71.19	6.41	9.0	6.41	9.0	0.00	0.0	84.00
7	PY10854	27101990	JD GREASE GARD PREMI	1.00			290.00	245.76	22.12	9.0	22.12	9.0	0.00	0.0	290.00
8	R276703	87089900	TANK. TANK. COOLANT O	1.00			193.00	163.56	14.72	9.0	14.72	9.0	0.00	0.0	193.00
9	R197038	73182400	COTTER PIN	1.00			11.00	9.32	0.84	9.0	0.84	9.0	0.00	0.0	11.00
10	R140438	87089900	BEARING CAP. HUB	1.00			84.00	71.19	6.41	9.0	6.41	9.0	0.00	0.0	84.00
<b>Spares Total</b>				<b>14</b>				<b>4,517.78</b>	<b>406.61</b>		<b>406.61</b>		<b>0.00</b>		<b>5,331.00</b>
<b>Services</b>															
1	Front Hub Greasing / Bearing / Seal - One Side Site 20456719			1			350.00	296.61	26.69	9.0	26.69	9.0	0.00	0.0	350.00
2	Front Hub Greasing / Bearing / Seal - One Side Site 20456719			1			350.00	296.61	26.69	9.0	26.69	9.0	0.00	0.0	350.00
<b>Service Total</b>				<b>2.00</b>	0.00	0.00		<b>593.22</b>	<b>53.38</b>		<b>53.38</b>		<b>0.00</b>		<b>700.00</b>
<b>Grand Total :</b>				<b>16</b>				<b>5,111.01</b>	<b>459.99</b>		<b>459.99</b>		<b>0.00</b>		<b>6,031.00</b>

GSTIN:36AAECV5358D1Z9  
 CIN-U34103TG2013PTC089369

**Rupees :** Six Thousand and Thirty One Only  
 Note : Parts once sold will not be taken back or exchange.

All Subject to HYDERABAD Jurisdiction only.

Bank Processing Charges :

**Spares.Total :** 5,331.00  
**Lab.Charges :** 700.00  
**Round Off :** 0.00  
**Total :** 6,031.00

This is Computer Generated Invoice Signature not Required