

# VENKAT SAI ENTERPRISES PRIVATE LIMITED

GSTIN : 36AAECV5358D1Z9

Website : <https://www.venkatsaienterprises.com>

(Authorised Dealer for JOHN DEERE INDIA PRIVATE LIMITED)

**Branch:** 10-120/3/d2, Janagaon Road, Palakurthy, Dist: Janagaon,TS-506317

Admin & Regd Off:8-6-300 Kothirampur Karimnagar Telangana 505001

## JOB CARD GST INVOICE

**C.Code :** 34024  
**C.Name :** BHUKYA EMLLA  
 S/o or W/o : SAKRU  
 H.NO:2-30. V:MEKALA THANDA. KONDAPURAM  
 M:PALAKURTHY  
 JANGAON  
 Telangana

**Bill No. :** PLK-JI-27 54  
**Date :** 10-04-2026  
**JC NO :** PLKCSJCB27 5  
**JC Date :** 10-Apr-26 12:00:00 AM  
**Chassis No :** 1PY5310ETLA049202  
**Model No :** 5310 TSS  
**Reg No :**

-.....  
 PH: 9618564314

**GSTIN :**

SNo	Item Code	HSN	Item Description	Qty	Wty	Foc	Unit Rate	Assesable Value	CGST		SGST		IGST		Amount	
									Rs	%	Rs	%	Rs	%		
1	PY10850	27101990	ENGINE OIL (8.5L CAN)	1.00			3,430.00	2,906.78	261.61	9.0	261.61	9.0	0.00	0.0	3,430.00	
2	R120247	73182200	RING. WASHER	1.00			30.00	25.42	2.29	9.0	2.29	9.0	0.00	0.0	30.00	
3	R140561	87089900	WASHER	2.00			12.00	20.34	1.83	9.0	1.83	9.0	0.00	0.0	24.00	
4	R503808	87089900	DRAIN PLUG. PLUG. DRAI	1.00			66.00	55.93	5.03	9.0	5.03	9.0	0.00	0.0	66.00	
5	RE507204	84212300	OIL FILTER	1.00			390.00	330.51	29.75	9.0	29.75	9.0	0.00	0.0	390.00	
6	RE508953	84212300	INSERT FILTER PRIMARY	1.00			125.00	105.93	9.53	9.0	9.53	9.0	0.00	0.0	125.00	
7	RE508954	84212300	INSERT FILTER SECONDA	1.00			132.00	111.86	10.07	9.0	10.07	9.0	0.00	0.0	132.00	
8	SJ20650	87089100	RADIATOR. ASSEMBLY AL	1.00			7,405.00	7,052.38	176.31	2.5	176.31	2.5	0.00	0.0	7,405.00	
9	PY0747	38200000	COOLANT 10 LIT CAN (NE	1.00			2,233.00	1,892.37	170.31	9.0	170.31	9.0	0.00	0.0	2,233.00	
10	RE507807	87089900	PIPE PLUG.	1.00			35.00	29.66	2.67	9.0	2.67	9.0	0.00	0.0	35.00	
<b>Spares Total</b>				<b>11</b>				<b>12,531.20</b>	<b>669.40</b>			<b>669.40</b>		<b>0.00</b>		<b>13,870.00</b>
<b>Services</b>																
1	Radiator Replacement / Coolant Replacement- HSN Code :998719			1			350.00	296.61	26.69	9.0	26.69	9.0	0.00	0.0	350.00	
2	Hydraulic Arm / Seals Replacement 1 side-5E HSN Code :998719			1			500.00	423.73	38.14	9.0	38.14	9.0	0.00	0.0	500.00	
3	Fan Belt-5E HSN Code :998719			1			150.00	127.12	11.44	9.0	11.44	9.0	0.00	0.0	150.00	
<b>Service Total</b>				<b>3.00</b>	0.00	0.00		<b>847.46</b>	<b>76.27</b>			<b>76.27</b>		<b>0.00</b>		<b>1,000.00</b>
<b>Grand Total :</b>				<b>14</b>				<b>13,378.64</b>	<b>745.67</b>			<b>745.67</b>		<b>0.00</b>		<b>14,870.00</b>

GSTIN:36AAECV5358D1Z9  
 CIN-U34103TG2013PTC089369

**Rupees :** Fourteen Thousand Eight Hundred and Seventy Only  
 Note : Parts once sold will not be taken back or exchange.

Subject to KARIMNAGAR Jurisdiction

Bank Processing Charges :

**Spares.Total :** 13,870.00  
**Lab.Charges :** 1,000.00  
**Round Off :** 0.00  
**Total :** 14,870.00

This is Computer Generated Invoice Signature not Required