

VENKAT SAI ENTERPRISES PRIVATE LIMITED

GSTIN : 36AAECV5358D1Z9

Website : <https://www.venkatsaienterprises.com>

(Authorised Dealer for JOHN DEERE INDIA PRIVATE LIMITED)

Branch: Bhoopalapally Road- Beside: Indian Oil Petrol Pump, PARKAL, 5061
Admin & Regd Off:8-6-300 Kothirampur Karimnagar Telangana 505001

JOB CARD GST INVOICE

C.Code : 58575
C.Name : YARA RAMESH
S/o or W/o : RAYAMALLU
H.No.6-27,RAMAKRISHNAPUR
NADIKUDA
HANUMAKONDA -506391
Telangana PH: 9121846467

Bill No. : PRL-JI-27 46
Date : 07-04-2026
JC NO : PRLFSJCB27 51
JC Date : 07-Apr-26 12:00:00 AM
Chassis No : 1VY5045DCSB055934
Model No : 5045 4WD V3 BKT F 9.5.20
Reg No :

GSTIN :

| SNo | Item Code | HSN | Item Description | Qty | Wty | Foc | Unit Rate | Assesable Value | CGST | | SGST | | IGST | | Amount |
|----------------------|---|----------|----------------------------|-------------|------|------|-----------|-----------------|---------------|-----|---------------|-----|-------------|-----|-----------------|
| | | | | | | | | | Rs | % | Rs | % | Rs | % | |
| 1 | PYS10242 | 27101990 | PLUS-50 Premium Engine | 1.00 | | | 3,984.00 | 3,376.27 | 303.86 | 9.0 | 303.86 | 9.0 | 0.00 | 0.0 | 3,984.00 |
| 2 | DZ114256 | 84212300 | Oil Filter | 1.00 | | | 1,060.00 | 898.31 | 80.85 | 9.0 | 80.85 | 9.0 | 0.00 | 0.0 | 1,060.00 |
| 3 | DZ127607 | 84212300 | Fuel Filter, INSERT FILTER | 1.00 | | | 286.00 | 242.37 | 21.81 | 9.0 | 21.81 | 9.0 | 0.00 | 0.0 | 286.00 |
| 4 | R120247 | 73182200 | RING. WASHER | 1.00 | | | 30.00 | 25.42 | 2.29 | 9.0 | 2.29 | 9.0 | 0.00 | 0.0 | 30.00 |
| 5 | R503808 | 87089900 | DRAIN PLUG. PLUG. DRAI | 1.00 | | | 66.00 | 55.93 | 5.03 | 9.0 | 5.03 | 9.0 | 0.00 | 0.0 | 66.00 |
| 6 | SJ11062 | 84219900 | FILTER ELEMENT. FILTER | 1.00 | | | 1,009.00 | 855.08 | 76.96 | 9.0 | 76.96 | 9.0 | 0.00 | 0.0 | 1,009.00 |
| Spares Total | | | | 6 | | | | 5,453.40 | 490.80 | | 490.80 | | 0.00 | | 6,435.00 |
| Services | | | | | | | | | | | | | | | |
| 1 | 2nd Free Maintenance HSN Code :998719 | | | | | 1 | 350.00 | 0.00 | 0.00 | 9.0 | 0.00 | 9.0 | 0.00 | 0.0 | 0.00 |
| 2 | Transmission Oil filter Replacement HSN Code :998719 | | | | | 1 | 100.00 | 0.00 | 0.00 | 9.0 | 0.00 | 9.0 | 0.00 | 0.0 | 0.00 |
| Service Total | | | | 0.00 | 0.00 | 2.00 | | .00 | 0.00 | | 0.00 | | 0.00 | | 0.00 |
| Grand Total : | | | | 8 | | | | 5,453.38 | 490.80 | | 490.80 | | 0.00 | | 6,435.00 |

GSTIN:36AAECV5358D1Z9
CIN-U34103TG2013PTC089369

Rupees : Six Thousand Four Hundred and Thirty Five Only
Note : Parts once sold will not be taken back or exchange.

Subject to KARIMNAGAR Jurisdiction

Bank Processing Charges :

Spares.Total : 6,435.00
Lab.Charges : 0.00
Round Off : 0.00
Total : 6,435.00

This is Computer Generated Invoice Signature not Required